

# Oil Field Environmental Incident Summary

**Incident:** 20140115130805      **Date/Time of Notice:** 01/15/2014 12:55

**Responsible Party:** Oasis Petroleum

**Well Operator:** OASIS PETROLEUM NORTH AMERICA LLC

**Well Name:** ERVIN 5693 11-24T

**Field Name:** ALGER

**Well File #:** 23766

**Date Incident:** 1/13/2014      **Time Incident:** 1200

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 156

**Rng:** 93

**Sec:** 24

**Qtr:** NW NW

**Location Description:** Oil mist covered an area approx. 60 X 200 into adjacent field.

**Submitted By:** Jared Iverson

**Received By:**

**Contact Person:** Jared Iverson  
1001 FANNIN STE 1500  
HOUSTON, TX 77002

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1 Miles

**Distance Nearest Water Well:** 1 Miles

**Type of Incident:** Stuffing Box Leak

**Release Contained in Dike:** No

**Reported to NRC:** Unknown

|       | Spilled | Units   | Recovered | Units   | Followup | Units   |
|-------|---------|---------|-----------|---------|----------|---------|
| Oil   | 4       | barrels | 3         | barrels | 3        | barrels |
| Brine | 0       | barrels | 0         | barrels |          |         |
| Other | 0       | barrels | 0         | barrels |          |         |

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 3/24/2016

**Clean Up Concluded:** 9/19/2014

**Risk Evaluation:**

None

**Areal Extent:**

60 X 200

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

Strata is onsite conducting the clean up.

**Wastes Disposal Location:** Clean Harbors.

**Agencies Involved:**

**Updates**

---

**Date:** 1/15/2014    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Oil spray off location from stuffing box leak. Followup is necessary.

---

**Date:** 1/24/2014    **Status:** Awaiting Documentation

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

1/24/2014 at 11:09, on location. SE of wellpad has been tilled up, no noticeable stains within tilled area or on snow along south border of tilled area, bordering train track right-of-way. According to report contact, spray went towards a line of trees. After inspecting treeline, a faint stain was noted on trees in the middle and southern sections. Notified report contact and recommended discussing remediation options for trees with landowner (note: according to contact, landowner was informed previously of incident). Report contact will notify with update once company land department has information from landowner.

---

**Date:** 5/5/2014    **Status:** Correspondence

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Phone call with report contact for update; report contact will check and email back an update report.

---

**Date:** 5/6/2014    **Status:** Correspondence

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Email from report contact; they have talked with the landowner and will be monitoring the treeline.

---

**Date:** 9/19/2014    **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

9/19/2014 at 14:17, on location. Most of trees in treeline appear alive. Some trees appear dead due to lack of foliage, but based on dead trees' scattered locations throughout the treeline, they do not appear to have died due to incident. Trees, including dead trees, in impacted area show no remaining stains. Other vegetation shows no visible impact.